

General Environmental Incident Summary

Incident: 1895 **Date/Time Notice:** 3/26/2013 1523 **DEM Incident No:**
Responsible Party: Rolfson Oil, Inc.
Date Incident: 2/27/2013 **Time Incident:** 2230 **Duration:** 60 minutes
County: McKenzie **Twp:** 147 **Rng:** 99 **Sec:** 25 **Qtr:** SW NW SW
Lat: 47.52356 **Long:** -103.23740 **Method:** Derived from TRS
Location Description: Mile Marker 121, Hwy 85, Grassy Butte, ND

Submitted By: Andrew Shaffer **Affiliation:**
Address:
City: **State:** **Zip:**

Received By:

Contact Person: Andrew Shaffer
202 3rd Ave. SW
Watford City, ND 58854

Distance Nearest Occupied Building: 1 Miles

Type of Incident: Vehicle Accident

Description of Released Contaminant: Dyed Diesel fuel

Volume Spilled: 5000.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Yes

Cause of Incident:

Single vehicle accident. Icy road conditions caused trailer to fish tail, break off from truck, and flip over into a ditch.

Risk Evaluation:

Potential fire hazard.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

The ground was frozen so soil impact limited. Clean up was immediate. No nearby waterways.

Action Taken or Planned:

Clean up company called to contain spill, soil was excavated. There were no nearby homes or person so no evacuation was necessary.

Wastes Disposal Location: Clean up company hauled the waste to their proper disposal site.

Agencies Involved: State Highway Patrol, Local Law Enforcement, Local Emergency Manager, EPA

Updates

Date: 2/28/2013 ***Status:*** Inspection

Author: Roberts, Kris

Updated Volume:

Notes:

Roberts on location, approximately 10:00. Fuel running down ditch toward cattle pasture crossing under Hwy 85 on edge of Badlands, North Unit.

Date: 7/31/2013 ***Status:*** Inspection

Author: Roberts, Kris

Updated Volume:

Notes:

Clean up and remediation acceptable. Closure letter drafted and sent.